



West Coast Tank Recovery

Oil Tank Detection | Oil Tank Removal | Contaminated Soil Removal

4455 Nottingham Rd. North Vancouver BC V7K 2N4

W: wctankrecovery.net

P: (604) 628-8786

LETTER OF COMPLIANCE **(Certificate of Oil Tank Inspection)**

May 7th 2015


Roland Lewis
1909 Queensbury Ave.
North Vancouver, BC
V7L 3W1

Dear Roland Lewis:

We have performed a TW6 M-2 scope metal detection scan for an underground storage tank (UST) at the above address.

No visual signs of fill/vent pipes were present

Due to the result of the scan which may have included probing and exploratory digging we are confident that there is no underground storage tank buried on the above property.



Martin Wouters

Disclaimer

As with any technical equipment or precision devices, results are rarely 100% conclusive. West Coast Tank Recovery Incorporated will not accept any lawsuits and or court actions in any way for the future discovery of underground storage tanks, especially ones found under the original structure, additions added to the original structure, under storage sheds or detached buildings, under swimming pools, concreted walkways, driveways or slabs, especially ones which contain rebar or any other metal construction materials, under larger trees, plants, shrubs, decks or patios with minimal clearance.