



West Coast Tank Recovery

Oil Tank Detection | Oil Tank Removal | Contaminated Soil Removal

4455 Nottingham Rd. North Vancouver BC V7K 2N4

W: wctankrecovery.net

P: (604) 628-8786

LETTER OF COMPLIANCE **(Certificate of Oil Tank Inspection)**

May 26th 2015

Roland Lewis
4125 Burkeridge Pl.
West Vancouver, BC
V7V 3N1

Dear Roland Lewis:

We have performed a TW6 M-2 scope metal detection scan for an underground storage tank (UST) in available areas at the above address.

No visual signs of fill/vent pipes were present.

Due to the result of the scan which may have included probing and exploratory digging we are confident that there is no underground storage tank buried on the above property.

Martin Wouters
Owner/Operator

Disclaimer

As with any technical equipment or precision devices, results are rarely 100% conclusive. West Coast Tank Recovery Incorporated will not accept any liability, lawsuits and or court actions in any way for the future discovery of underground storage tanks-- especially ones found under the original structure, additions added to the original structure, under storage sheds or detached buildings, under swimming pools, concreted walkways, driveways, paving stones or slabs (especially slabs which contain rebar or any other metal construction materials), under large trees, plants, shrubs, decks or patios with minimal clearance.