



# West Coast Tank Recovery

Oil Tank Detection | Oil Tank Removal | Contaminated Soil Removal

4455 Nottingham Rd. North Vancouver BC V7K 2N4

w: [wctankrecovery.net](http://wctankrecovery.net)

p: (604) 628-8786

## **LETTER OF COMPLIANCE** *(Certificate of Oil Tank Inspection)*

September 3<sup>rd</sup> 2015

**Roland Lewis**  
158 E. 27<sup>th</sup> Street  
North Vancouver, BC  
V7N 1S7

Dear Roland Lewis:

We have performed a metal detection scan in available areas using a Fisher TW6 M-Scope and Schonstedt GA92-XT for an underground heating Oil Tank at the above address.

*No visual signs of fill or vent pipes were found on the property.*

Due to the result of the scan which may have included probing and exploratory digging we are confident that there is no underground heating Oil Tank buried on the above property.

**Martin Wouters**  
Owner/Operator

#### **Disclaimer**

As with any technical equipment or precision devices, results are rarely 100% conclusive.

West Coast Tank Recovery Incorporated will not accept any liability, lawsuits and or court actions in any way for the future discovery of underground storage tanks anywhere on the above property-- especially ones found under the original structure, additions added to the original structure, under storage sheds or detached buildings, vehicles, swimming pools, concreted walkways, driveways, paving stones or slabs (especially slabs which contain rebar or any other metal construction materials), under large trees, plants, shrubs, decks or patios with minimal clearance.